ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra

Street ID	Street Name	Significant Landmark
W0107, W0084, W0033, W0028, W0035, W0088, W0086, W	Subhash Chandra Bose Lyt, NA	1st main and 4th Cross Nanjappa Layout area

Segment No.	Total Length (m)
10/C-W0107/S082452	305.40

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	305.40	77.556539	13.066312	77.557826	13.068323	W0035	W0088

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at 1st main and 4th Cross Nanjappa Layout area in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahan	2500000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Not a Tender	Improvements to Roads and Drains at 1st main and 4th Cross Nanjappa Layout area in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	010-17-000002

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/107/2016-17	19/08/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
19/08/2016	18/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00

Phone No.	E-Mail ID

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
7		MADHAVA RAO
Date of Inspection	**Remarks**	
07/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0107, W0084, W0033, W0028,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	07/12/2016	06/01/2017	COMPLETED
SE	VASU K M	07/12/2016	06/01/2017	COMPLETED
EE	YARAPPA REDDY	07/12/2016	06/01/2017	COMPLETED
AEE	SHIVAKUMAR	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED
AE	MADHAV RAO	07/12/2016	06/01/2017	COMPLETED